

## **Technical Data Sheet**

### **Hi-Spot Blue**

#### **FEATURES**

- Intensely blue, soft, uniform paste.
- Spreads easily and evenly to show high spots on bearings and contact surfaces.
- A thin coating my be left on the surface day in and day out and will not dry.
- The blue film remains in a pliable and transferable and in condition for months.
- Excellent adhesion to metal and other substrates.
- Does not contain any reportable amounts of Xylene.

#### **MATERIALS COMPATIBILITY**

- Safe on most surfaces.
- Removable with Dykem® Remover & Cleaner.
- Surface tests should be run to determine compatibility prior to use.

# AVAILABLE IN: PART# 0.55 oz. tube 83307

#### HEALTH AND SAFETY

- Slightly combustible liquid and vapor. Keep away from heat, sparks and flame. Use only with adequate ventilation. Avoid contact with skin and eyes.
- Refer to SDS (Safety Data Sheet) for complete information on health and safety. Visit our website to obtain SDS.

### PHYSICAL PROPERTIES

Appearance: Blue viscous liquid.

Odor: Mild
Specific gravity: >1
VOC level: 0%
Flash point: >200°F
Dry Time: Will not dry

